```
0.6.3 sub revision(11 Feb 2019):
-------------------------------------------------------------------
```

Simple improvements that make the boards easier to solder:

- improved relay footprint to support G and F type

Mechanical changes:

- BNC replaced by SMA connector

Schematics changes:

- none